



Wymagane jest użycie klucza płaskiego nr 10





Zaleca się użycie rękawic.

400 mm

GŁĘBOKOŚĆ



H (mm)	337 mm	537 mm
1950	3	3
2550	3	5
3000	3	6



600 mm

GŁĘBOKOŚĆ



H (mm)	537 mm	805 mm
1950	3	2
2550	4	3
3000	4	4




800 & 1000 mm

GŁĘBOKOŚĆ


H (mm)	(800) 737 mm (1000) 937 mm	(800) 1015 mm (1000) 1170 mm
1950	3	2
2550	4	3
3000	4	3




1



2



3



Pręt stężący używany tylko do szerokości 2200 mm

4

